

## You tried to stretch your Soft-Serve mix to go a bit further

Some machine operators sometimes add extra water or milk to the Soft-Serve mix when they mix it up, trying to make a few extra cones and of course more money from every batch. This should not be attempted as it can actually break the machine. This is because the extra water can cause the machine to freeze up, resulting in bent or broken beater assemblies, broken freezer doors and scarred freezing cylinders (barrels). On some machines it can cost up to approximately \$10,000 to replace a barrel! It will be a very expensive mistake!

